1C11 TEST BIT AND BRANCH

A. PURPOSE

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

B. LOADING PROCEDURES

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.
WHEN RUNNING FROM TAPE ENTER A 1 IN S 56 1256 .

WHEN RUNNING THIS TEST SEPARATELY FROM CARDS ADD A BLANK CARD BEHIND THE TEST DECK. THIS IS NECESSARY TO ELIMINATE THE PROGRAM FROM HANGING UP IN AN OVERLAP LOOP AND WILL INSURE PROPER PROCESSING OF THE LAST DETAIL CARD.

C. PROGRAM CONTROL

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

D. TEST PROCEDURE

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

E. STOPS

816 - PAR ERROR
831 - BRANCH ERROR
973 - I/O ERROR
AFTER STOP, PUSH START TO CONTINUE

F. PRINTOUTS

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.