



6A, B, C, D-6

- 16C6 ACTIVATE STORAGE
- 111CS NOT PRT READY
- (NOTE 1) NOT PRINTER HALTED
- 117AS SPACE SKIP GATE
- 21D2 I-O OPS
- 18A6 I RING OP
- TIME 060-045
- 11604 CARRIAGE INTERLOCK
- 1Q4D6 RUN TRIGGER
- TIME 045-060
- 15D6 NOT PROCESS CK

99.99.91.1

DATE	CHANGE NO.	DATE	CHANGE NO.	INTERNATIONAL BUSINESS MACHINES CORP
4-10-62	11383CD			NAME INHIBIT CHECK AND
4-2-63	114144C	31.7.62	TA 1370K	METER CIRCUITS
9-25-63	118584	15.11.63	TA 604D	DESIGN TYPE
				DETAIL SCALE NONE
				CHECK DRAW VE 1-5-62
				APPRO CHECK MW 1-0-62

NOTE 1: USED ON PF MACHINES BELOW SERIAL NUMBER 25,000  
 2: OUTPUT OF SINGLE SHOT (400 M.L.SEC.) IS A NEGATIVE SIGNAL

130011