

PROGRAM LISTING

FORMS SKIPPING BLOCK 2010A

,008012,019,026030L0653681001,008012,001100118361080AB421/340080 1 OF 2 2010A 02  
 ,037044N000,340344,348349,357,361368/333080 PROG. CHAIN. ROUTINE 2 OF 2 2010A 03  
 L057S4510012,049L0772772/27720/40/600/80L/892702/2702413 CARD 1 OF 3 2010A 04  
 ,019026,033,040044,051051/340001 TITLE PRINT ROUTINE CARD 2 OF 3 2010A 05  
 ,S01S05,S12,S13S17,S18S25,S29S36,S37S41,S45/333080 CARD 3 OF 3 2010A 06

LOAD	INST	ADDR	ADDR	CP	A	B	REMARKS	
396	377	B	389			5611	USE WHEN TESTS ARE RUN FROM TAPE	07
404	385	D	388				''	08
408	389	N	000				''	09
412	393	M	360			392	''	10
419	400	/	332				CLEAR PRINT AREA	11
423	404	/					''	12
424	405	L	699			S22	MODIFY TITLE PRINT TO SKIP HEADINGS	13
431	412	B	S00			S521	BR TO TITLE PRINT ROUTINE IF 1 IN S52	14
439	420	,	201				SET WORD MARK IN PRINT AREA	15
443	424	M	941			332	MOVE HYPHEN INTO 332	16
450	431	M	332			331	MOVE HYPHEN INTO ALL PRINT POSITIONS	17
457	438	L	920			250	LOAD SKIP TO 1 IMMEDIATE	18
464	445	F	1				FORMS CONTROL	19
466	447	2					PRINT OPERATION COMMENT	20
467	448	D	942			240	LOAD SKIP TO 2 IMMEDIATE	21
474	455	F	2				FORMS CONTROL	22
476	457	2					PRINT OPERATION COMMENT	23
477	458	D	943			240	LOAD SKIP TO 3 IMMEDIATE	24
484	465	F	3				FORMS CONTROL	25
486	467	2					PRINT OPERATION COMMENT	26
487	468	D	944			240	LOAD SKIP TO 4 IMMEDIATE	27
494	475	F	4				FORMS CONTROL	28
496	477	2					PRINT OPERATION COMMENT	29
497	478	D	945			240	LOAD SKIP TO 5 IMMEDIATE	30
504	485	F	5				FORMS CONTROL	31
506	487	2					PRINT OPERATION COMMENT	32
507	488	D	946			240	LOAD SKIP TO 6 IMMEDIATE	33
514	495	F	6				FORMS CONTROL	34
516	497	2					PRINT OPERATION COMMENT	35
517	498	D	947			240	LOAD SKIP TO 7 IMMEDIATE	36
524	505	F	7				FORMS CONTROL	37
526	507	2					PRINT OPERATION COMMENT	38
527	508	D	948			240	LOAD SKIP TO 8 IMMEDIATE	39
524	515	F	8				FORMS CONTROL	40
536	517	2					PRINT OPERATION COMMENT	41
537	518	D	949			240	LOAD SKIP TO 9 IMMEDIATE	42
544	525	F	9				FORMS CONTROL	43
546	527	2					PRINT OPERATION COMMENT	44
547	528	M	951			240	LOAD SKIP TO 10 IMMEDIATE	45
554	535	F	0				FORMS CONTROL	46
556	537	2					PRINT OPERATION COMMENT	47

2010A-5

DATE								
ENG CHG NO								