

1401 DATA PROCESSING SYSTEM
DIAGNOSTIC FUNCTION TEST

1C11 TEST BIT AND BRANCH

A. PURPOSE

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

B. LOADING PROCEDURES

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.
 WHEN RUNNING FROM TAPE ENTER A 1 IN S 56 1256 .

WHEN RUNNING THIS TEST SEPARATELY FROM CARDS ADD A BLANK CARD BEHIND THE TEST DECK. THIS IS NECESSARY TO ELIMINATE THE PROGRAM FROM HANGING UP IN AN OVERLAP LOOP AND WILL INSURE PROPER PROCESSING OF THE LAST DETAIL CARD.

C. PROGRAM CONTROL

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

D. TEST PROCEDURE

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

E. STOPS

816 - PAR ERROR
 831 - BRANCH ERROR
 973 - I/O ERROR
 AFTER STOP, PUSH START TO CONTINUE

F. PRINTOUTS

SEE GENERAL DESCRIPTION INCLUDED IN INTRODUCTION.

DATE	4-3-62	5-25-62						
ENG. CHG. NO.	115276	115276C						